

# HEATH TECNA

## Job Posting

**Title:** Quality Inspector- Receiving  
**Reports To:** Quality Control Supervisor  
**Application Deadline:** Until Filled  
**Posting:** Internal/External

**Responsibilities:** The Quality Assurance Inspector I physically inspects aircraft components and hardware to ensure that workmanship and raw materials meets acceptable standards of quality and/or airworthiness, and reviews associated documentation to ensure that all design data (dimensional, material, appearance, special processes) are substantiated, and that aircraft components are in an airworthy condition with all required documentation properly completed and filed.

**Requirements:**

- High School diploma or GED required. Technical or College degree in applicable field preferred.
- Experience in a manufacturing or quality environment.
- Strong working knowledge of engineering drawings / specifications and basic quality procedures.
- Must be proficient in the utilization of Federal Aviation Regulations, FAA forms and documents.
- Must be proficient in the use of precision measurement equipment; micrometers, calipers, height gauges, dial indicators, surface roughness gauges, etc.
- Strong written and verbal communication skills. Strong computer skills.
- Must be able to prioritize tasks, work independently and efficiently.
- Lifting requirement: 30 lbs.
- Ability to work any shift and holidays on rotation, if required.

**Equal Opportunity Employer**